

ECA0100,UNITED BULK CARRIERS,UBC MIAMI,CYPRUS,9421130,06/12/2015,PUERTO LIMON  
ANCHORAGE,PORT ARTHUR TX;BRIDGETOWN,PUERTO LIMON,NA,NA,NA,06/18/2015,01:30,2.82,20,PORT  
ARTHUR TX,Y,Y,1,NA,NA,NA,NA,06/22/2015,12:00,Y,3,3,Y,4,MR. PAWEL  
GORALCZYK,OPERATIONS@UNITEDBULKCARRIERS.COM,6109952600,VESSEL WAS UNEMPLOYED WAITING AT  
PUERTO LIMON ANCHORAGE. WHEN NEW VOYAGE HAS BEEN FIXED CURRENT STOCK OF COMPLIANT  
BUNKER WAS SUFFICIENT TO SAFELY REACH PORT ARTHUR ANCHORAGE FOR PROPULSION AND POWER  
SUPPLY PURPOSE. WE FILE THIS REPORT IN CASE OF ANY UNEXPECTED DELAY TO THE VESSEL IN  
WHICH CASE VESSEL HAS TO USE NON-COMPLIANT BUNKER FOR PROPULSION PURPOSE FOR SHORT  
PERIOD AND SAVE SOME FUEL FOR POWER SUPPLY WHILE WAITING.